

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L2	16	(US-20070216225-\$ or US-20070024124-\$).did. or (US-5710465-\$ or US-5990573-\$ or US-6218740-\$ or US-6744147-\$ or US-4720763-\$ or US-6236552-\$ or US-5107391-\$ or US-7248451-\$ or US-7016171-\$ or US-6798633-\$ or US-5317475-\$ or US-5402302-\$ or US-5442515-\$ or US-5793599-\$).did.	US-PGPUB; USPAT	OR	OFF	2008/02/11 11:08
L3	3	2 and (printed PCB)	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/11 11:08
L4	1795	(diagnosis diagnostic\$2) same abnormality and vehicle	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/11 11:23
L5	2905	(307/10.1).CCLS.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2008/02/11 11:24
L6	21	4 and L5	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/11 11:24
S1	1	("20070216225").PN.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2007/10/13 14:25
S2	9	((("20020180271") or ("6476515") or ("5710465") or ("5637933") or ("20040021371") or ("60465131") or ("5990573") or ("6218740") or ("6744147") or ("6577025"))).PN.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2007/10/13 14:00
S3	27	relay same heat same voltage with (stepped adj down lowered decreased)	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:03

S4	0	relay same switching adj voltage same holding adj voltage	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:04
S5	181	relay same switching adj voltage	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:04
S6	2	relay same switching adj voltage same hold\$3 adj voltage	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:05
S7	3078	relay and heat and voltage with (step stepped stepping)	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:06
S8	970	relay and heat and voltage with (step stepped stepping) with (down lowered decreased)	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:08
S9	232	heat and voltage with (step stepped stepping) with (down lowered decreased) same relay	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:10
S10	20	relay same closing adj voltage	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:10
S11	2862	(307/10.1).CCLS.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2007/10/13 14:18
S12	94	heat same excess same voltage same step\$5	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:23
S13	1	relay same pull adj in	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:23
S14	0	hold adj operation same pull adj in	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:24
S15	2173	hold adj operation	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:24
S16	0	hold adj operation same intial adj closing	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:24
S17	1385	junction adj box and relay and operation	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:25
S18	1106	(307/9.1).CCLS.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2007/10/13 14:25

S19	0	("008and9").PN.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2007/10/13 14:25
S20	9	S17 and S18	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/13 14:26
S21	9014	relay same heat	US-PGPUB; USPAT; EPO	OR	ON	2007/10/13 14:27
S22	2147	S21 same voltage	US-PGPUB; USPAT; EPO	OR	ON	2007/10/13 14:27
S23	789	S22 and controller	US-PGPUB; USPAT; EPO	OR	ON	2007/10/13 14:28
S24	41	("3512045" "3611038" "3800121" "4034267" "4093977" "4115829" "4173774" "4205358" "4271444" "4347540" "4672501" "4685022" "4688134" "4783713" "5019956" "5047890" "5241443" "5309311" "5334912" "5361183" "5521787" "5552952" "5644510" "5745322" "5835322" "5966280" "5969921" "6002563" "6091591" "6246332" "6246556" "6249230" "6266219" "6278381" "6278596" "6320731" "6327124" "6329785" "6583975").PN. OR ("7016171").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/10/15 09:02
S25	10	("3748537" "3884318" "4410808").PN. OR ("5107391").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/10/15 09:03
S26	13	("3634733" "3852646" "3904938" "4355619" "4729056" "4797779" "4812945" "5381297" "5422780" "5469825" "5568349" "5793599"). PN. OR ("6236552"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/10/15 09:05

S27	16	(US-20070216225-\$ or US-20070024124-\$).did. or (US-5710465-\$ or US-5990573-\$ or US-6218740-\$ or US-6744147-\$ or US-4720763-\$ or US-6236552-\$ or US-5107391-\$ or US-7248451-\$ or US-7016171-\$ or US-6798633-\$ or US-5317475-\$ or US-5402302-\$ or US-5442515-\$ or US-5793599-\$).did.	US-PGPUB; USPAT	OR	OFF	2007/10/15 12:27
S28	3	S27 and (error warning message display)	US-PGPUB; USPAT	OR	OFF	2007/10/15 12:32
S29	21015	sufficient adj power	US-PGPUB; USPAT	OR	OFF	2007/10/15 12:32
S30	1182	S29 same (error warning message display)	US-PGPUB; USPAT	OR	OFF	2007/10/15 12:32
S31	41452	("307").CLAS.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2007/10/15 12:32
S32	28	S30 and S31	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/15 12:35
S33	5	vehicle same low adj battery and load adj shedding	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/15 12:36
S34	11	vehicle and low adj battery and load adj shedding	US-PGPUB; USPAT; EPO	OR	OFF	2007/10/15 16:46
S35	458	(307/126).CCLS.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2007/10/15 16:46

2/11/2008 12:33:38 PM

C:\Documents and Settings\mrutlandwallis\My Documents\EAST\Workspaces\11276840 vehicle junction box with voltage connection control.wsp